

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

			(Subm	iit 2 copies to at	ove addres	SS)		<i>.</i>	
Date of Test	5-2	5-20-2010 Operator			Energen Resources			3003923796	
Property Name	· (CULLINS	FEDERAL 4	Locatio	Location: Unit M Section		ownship 24	Range 3	
		(Well Name	and Number)						
Pressure (Shu	it-in or Proc	lucing)	Tubing _	155 Interme	diate	Casing <u>/</u> /	35 Bradenh	ead <u>Ø</u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	HERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
	Bradenhead			Interme	diate		Bradenhead	Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	a	105				Steady Flow			
10 minutes	0	105				Surges			
15 minutes	<u> </u>	105				Down to Nothing	×		
20 minutes		103				No Flow			
25 minutes		<u> </u>				Gas			
30 minutes	 -::::::::::::::::::::::::::::::::					Gas and Water			
5 minute SI	0	105				Water			
<u>If bradenhea</u>	ad flowed v	/ater, che	ck all of the d	lescriptions tha	t apply belo	ow:		12	
Clear	F	resh	Sa	ılty	Sulfur	Bla	ack 252 533	123456 A SEIVED 50 112010	
			α				REC	EIVED &	
5 Minute Sh	ut-in B	radenhead	<u> </u>	Intermediat			22.7	2010	
REMARKS:							SC ACCOUNT CONS	DIV. DIST 3	
							202	618117	
A.	#								
By	Ή			Wi	tness				
	Le	ase C	perator	<u> </u>					
		(Position)						