



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-17-10 Operator Energgen Resources API # 3003926305

Property Name JICARILLA 99 7A Location: Unit F Section 13 Township 26 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 70 Intermediate N/A Casing 90 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	90				Steady Flow	
10 minutes	0	90				Surges	
15 minutes	0	90				Down to Nothing	
20 minutes						No Flow	✓
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0	90				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear    Fresh    Salty    Sulfur    Black   

5 Minute Shut-in Bradenhead 0 Intermediate   

REMARKS:

Braden valve shut in May 14th.

By Ed. Edwards

Witness   

lease operator

(Position)

