



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/20/10 Operator Energen Resources API # 3003926586

Property Name JICARILLA 95 1C Location: Unit B Section 35 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 112 Intermediate N/A Casing 126 Bradenhead 12

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	126										
10 minutes	0	126										
15 minutes	0	126										
20 minutes												
25 minutes												
30 minutes												
5 minute SI	0	126										

Bradenhead Flowed	Intermediate Flowed

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black ✓ Brown

5 Minute Shut-in Bradenhead -0- Intermediate _____

REMARKS:

Braden valve shut-in May 14th
Brown foamy fluid came out of braden head

By Ed. Edwards Witness _____
lease operator
(Position)