



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energen Resources API # 3003926854

Property Name JICARILLA 95 7B Location: Unit F Section 36 Township 27 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 85 Intermediate N/A Casing 95 Bradenhead - 0 -

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	95				Steady Flow	
10 minutes	0	95				Surges	
15 minutes	0	95				Down to Nothing	✓
20 minutes						No Flow	
25 minutes						Gas	✓
30 minutes						Gas and Water	
5 minute SI	0	95				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear - Fresh - Salty - Sulfur - Black -

5 Minute Shut-in Bradenhead 0 Intermediate -

REMARKS:

B.H. Valve shut-in May 14th.

By Ed. Edwards

Witness -

lease operator  
(Position)

