



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energen Resources API # 3003926889

Property Name JICARILLA 95 5B Location: Unit N Section 25 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 81 Intermediate N/A Casing 95 Bradenhead -D-

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	95										
10 minutes	0	95										
15 minutes	0	95										
20 minutes									✓			
25 minutes												
30 minutes												
5 minute SI	0	95										

If bradenhead flowed water, check all of the descriptions that apply below:

Clear - Fresh - Salty - Sulfur - Black -

5 Minute Shut-in Bradenhead 0 Intermediate -

REMARKS:

Braden head valve shut in May 19th



By Ed. Edwards

Witness _____

lease operator

(Position)