

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			•			•			
Date of Test	5-20-2010 Op		Operator 	Energ	Energen Resources		API#	3003905430	
Property Name LINDRITH UNIT 45		H UNIT 45	Location: Unit O Section 14		Section 14	Township	24 Range 3		
		(Well Name	and Number)						
Pressure (Shu	t-in or Proc	ducing)	Tubing	Intermed	diate	Casing) <u> </u> Bra	denhead <u>Ø</u>	
OPEN	BRADENH	EAD AND	INTERMEDIAT	TE TO ATMOSP	HERE IND	IVIDUALLY FOR	15 MINUT	ES EACH	
Γ	Bradenhead			Interme	diate		Bradenhead Intermediate		
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowe		
5 minutes	15	75		- Diowdown	- Inomicor	Steady Flow	·		
10 minutes	_N	75				Surges	3		
15 minutes	8	75				Down to Nothing			
20 minutes		12		-		No Flow	v		
25 minutes						Gas	3		
30 minutes						Gas and Water	r		
5 minute SI	Ò	75				Wate	r		
If bradenhea	ad flowed w	/ater, che	ck all of the de	escriptions that	apply bel	ow:			
Clear Fresh Salty Sulfur Black									
5 Minute Shi	ut-in Bi	radenhea	<u> </u>	Intermediat .			2526273	RECEIVED SUM 2010	
REMARKS:	Nop	ressu	re an	brader 1.	ead		18. C.	CSOSET 57 17 37 CS. ST. SOSET 51 TV DIST 3 CS. ST. TV DIST 3 CS. ST. TV DIST 3 CS. ST. ST. ST. ST. ST. ST. ST. ST. ST. S	
	· ·				· · · · · · · · · · · · · · · · · · ·			(2020111015)	
					*				
ву	# 1	\ (10 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Opealos		ness				

(Position)