

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	5-2	5-21-2010 Operator		Energ	Energen Resources		API# 300	3905484
Property Name			H UNIT 46	Locatio	Location: Unit G Section 15		ownship 24	Range 3
Pressure (Sh	ut-in or Pro	ducing)	Tubing	Intermediate		Casing	Bradenh	ead <u>&</u>
OPEN	N BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSE	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH
·	Bradenhead			Interme	diate		Bradonhoad	Intermediate
Time 5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes 5 minute SI	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water	Flowed	Flowed
Clear								OIST : NO
Ву	# 1	ಲಿಕ್ಕ≀∟ (Position	Opeato	Wi	tness			