

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD **AZTEC, NM 87410** (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

			(Oubline	2 copies to at	ove addie	33)			
Date of Test	5-20	5-20-2010 Operator			Energen Resources			3003920092	
Property Name	e	LINDRITH UNIT 71			Location: Unit O Section 24			24 Range 3	
		(Well Name	and Number)	 _		·			
Pressure (Shu	ıt-in or Proc	lucing)	Tubing	Interme	diate	Casing	<u>C</u> Brad	enhead <u>5</u>	
OPEN	BRADENHI	EAD AND	INTERMEDIAT	E TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINUTE	S EACH	
	Bradenhead			Interme	diate		Bradenhe	ead Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed		
5 minutes	8	90				Steady Flow	<u> </u>		
10 minutes	8	80				Surges			
15 minutes	0	80				Down to Nothing			
20 minutes						No Flow			
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI	0	80				Water		15:11-123 15:11-123	
If bradenhe		vater, che	ck all of the de	escriptions tha	t apply bel Sulfur		ack 75.2622	PECEIVED BUN 2010 DIL CONS. DIV. DIST. 3 21202618117874	
5 Minute Sh	ut-in B	radenhea	d <u>Ø</u>	Intermediat			100	5/505er 81 Tr 20/c/	
REMARKS:	Not	Enoug	& Press	we to	Mess	we aft		ni nuta.	
ву //// (# 1	Para	Opeato	Wi	tness				

(Position)