



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-20-2010 Operator Energen Resources API # 3003921802

Property Name LINDRITH UNIT 95 Location: Unit G Section 10 Township 24 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) 115 Tubing 115 Intermediate Casing Ø Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Ø	Ø				Steady Flow		
10 minutes	Ø	Ø				Surges		
15 minutes	Ø	Ø				Down to Nothing		
20 minutes						No Flow	Ø	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	Ø	Ø				Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead Ø Intermediate

REMARKS:

No pressure on bradenhead



By

[Signature]

Witness

Lease Operator

(Position)