



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-20-2010 Operator Energen Resources API # 3003922742

Property Name LINDRITH UNIT 107 Location: Unit L Section 22 Township 24 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) 130 Intermediate      Casing 190 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>190</u>				Steady Flow	
10 minutes	<u>0</u>	<u>190</u>				Surges	
15 minutes	<u>0</u>	<u>190</u>				Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	<u>0</u>
30 minutes						Gas and Water	
5 minute SI	<u>0</u>	<u>190</u>				Water	


If bradenhead flowed water, check all of the descriptions that apply below:

Clear      Fresh      Salty      Sulfur      Black     

5 Minute Shut-in Bradenhead 0 Intermediate     

REMARKS:

No pressure on bradenhead



By [Signature] Witness     

Lease Operator  
(Position)