

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD **AZTEC, NM 87410** (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

			nmau <i>6</i>)	2 copies to an	ove_addre	SS)			·	
Date of Test	5-2	5-21-2010 Operator			Energen Resources			3003982323		
Property Name LINDRITH UNIT NP 3			UNIT NP 38	Location: Unit A Section 26			Township	24	Range	3
		(Well Name	and Number)						,	
Pressure (Shu	ut-in or Proc	ducing)	Tubing	Interme	diate	Casing _	50_ Br	adenh	ead <u>Ø</u>	~ ——
OPEN	BRADENH	EAD AND	INTERMEDIAT	E TO ATMOSF	HERE IND	IVIDUALLY FOI	R 15 MINU	TES E	ACH	
	Bradenhead			Interme	diate	,	Braden	head	Interme	diate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flow		Flowe	
5 minutes	075	50-				Steady Flo)w			
10 minutes	- (X)	50				Surge	es			
15 minutes	<u> </u>	50				Down to Nothir	ng			
20 minutes			<u></u> .		***	No Flo)w			
25 minutes						Ga	as			
30 minutes						Gas and Wat	er			
5 minute SI	B	50		-		Wat	er			
			eck all of the de							
Clear	F	resh _	Salty	/ <u></u>	Sulfur	E	Black			
5 Minute Sh	ut-in B	radenhea	d <u>Ø</u>	Intermediat			20 E	*	23456 A SED	o /
REMARKS:	No K	rre 55 i	re on	braderh	oak		252(201 <u>0</u> IV. DIST 3	910117.73
	· · · · · · · · · · · · · · · · · · ·						/5°, 011	-0110, D	IN DISE 3	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
						<u> </u>	<u>/5</u> /	-02 ₆ 1	8142	<u>/</u>
Ву	MA	Loss	2 Operat		tness					

(Position)