

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

**RECEIVED**

Sundry Notices and Reports on Wells

AUG 05 2010

1. Type of Well  
GAS

2. Name of Operator  
**BURLINGTON**  
RESOURCES OIL & GAS COMPANY LP

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

Surf: Unit A (NENE), 995' FNL & 990' FEL, Section 15, T27N, R6W, NMPM



Farmington Field Office  
Bureau of Land Management  
Lease Number  
SF-079365

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name  
San Juan 28-6 Unit

8. Well Name & Number  
San Juan 28-6 Unit 27

9. API Well No.  
30-039-07087

10. Field and Pool

11. Blanco MV  
County and State  
Rio Arriba Co., NM

**12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA**

Type of Submission

Type of Action

☐ Notice of Intent☐ Abandonment☐ Change of Plans☒ Other --☐ Cathodic Protection☒ Subsequent Report☐ Recompletion☐ New Construction☐ Plugging☐ Non-Routine Fracturing☐ Casing Repair☐ Water Shut off☒ Final Abandonment☐ Altering Casing☐ Conversion to Injection**13. Describe Proposed or Completed Operations**

Attached is a drawing of the placement of the cathodic ground bed, rectifier and cable for the subject well.

**14. I hereby certify that the foregoing is true and correct.**

Signed Brandie Blakley Brandie Blakley Title Staff Regulatory Technician Date 8-5-10

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


**ACCEPTED FOR RECORD**  
**AUG 06 2010**  
**FARMINGTON FIELD OFFICE**  
BY [Signature]

NMOC



## San Juan 28-6 Unit 27 & 209

Section 15, T27N, R6W, N.M.P.M., Rio Arriba County, NM



Drill new ground bed approximately 154' North West of #27 wellhead at staked location. Run new positive cable from existing rectifier to new ground bed at length listed below, and repair negative to wellhead.

Positive: 15'

Total Ditch: 15'

By: Steven Gillette  
Date: 5/25/10