



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 21-NOV-2010 Operator DULAN API #30-0 45-33217

Property Name HEAVY MONSTER Well No. 3 Location: Unit F Section 11 Township 24N Range 17W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	
Down to Nothing	
Nothing	
Gas	RCVD NOV 29 '10
Gas & Water	OIL CONS. DIV.
Water <u>✓</u>	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

bled off braden head through 1/4" hole for 15 min
flowed 1/4 gal, bled down to 2225

By [Signature]

Witness [Signature]

(Position)

E-mail address _____

CONDUCT ANNUAL BRADEN HEAD
TESTS UNTIL FURTHER NOTICE.
MONICA KUEHLING VERBALLY NOTIFIED
JOHN ALEXANDER ON 11-30-2010

KR