

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
505 334-6178 FAX: (505) 334-6178

(505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(,			
Date of Test	5-20	5-20-10 Operator		Energen Resources			API# 300	3003905373	
Property Nan	ne	LINDRI	TH UNIT 1	Location: Unit J Section 20			ownship 24	Range 2	
		(Well Name	e and Number)						
Pressure (Sh	nut-in or Pro	ducing)	Tubing	76 Interme	diate	Casing <u>//</u>	め Bradenh	ead <u> </u>	
OPE	N BRADENH	EAD AND	INTERMEDIAT	TE TO ATMOSF	HERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
	Bradenhead			Interme	diate		Bradenhead	Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	0	110				Steady Flow	<u></u>		
10 minutes	0	110	· · · · · · · · · · · · · · · · · · ·			Surges			
15 minutes	-0-	110				Down to Nothing			
20 minutes		700				No Flow			
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI	6	110				Water			
<u>lf bradenhe</u>	ead flowed v	vater, che	ck all of the de	escriptions tha	t apply bel	ow:			
Clear		resh	Salt		Sulfur	Bla	ick 331-	1234561090 ENED	
							REC	4 56	
5 Minute SI	hut-in B	radenhea	d <u>~</u>	Intermediat			REC	EIVED	
							256. MM	SOIO 3	
REMARKS:						•	OIL CONS.	DIV. DIST 3 3	
							1/23	, c) ^x)/	
							92025	181113	
			·				SOS OS		
	1. 0	•							
By Lut.	her flo	nce	, , , , , , , , , , , , , , , , , , , ,	Wit	tness				
LENS	S OP	SEAT	on			•			
									