



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/7/10 Operator Energen Resources API # 3003907983

Property Name SAN JUAN 32 5 UNIT 10 Location: Unit N Section 32 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65 Intermediate NA Casing 230 Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>230</u>	<u>NA</u>				
10 minutes	<u>0</u>	<u>230</u>	<u>NA</u>				
15 minutes	<u>0</u>	<u>230</u>	<u>NA</u>			<u>X</u>	
20 minutes	<u>0</u>	<u>230</u>	<u>NA</u>				
25 minutes	<u>0</u>	<u>230</u>	<u>NA</u>			<u>X</u>	
30 minutes	<u>0</u>	<u>230</u>	<u>NA</u>				
5 minute SI	<u>0</u>	<u>230</u>	<u>NA</u>				
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate NA

REMARKS: Slight Blow when opened. It blew quickly down
to nothing. No Build up during test.

By Richard Fairbanks Witness _____
Lease Operator
(Position)