

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emard.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-3-10 Operator Elm Ridge API #30-039-20053

Property Name SKelly Well No. 2 Location: Unit 35 Section 26 Township 7 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 141 Intermediate NA Casing 113 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	BRADENHEAD			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	NA	163		
10 min	0		163		
15 min	0		163		
20 min	0		163		
25 min	0		163		
30 min	0		163		

FLOW CHARACTERISTICS	
BRADENHEAD INTERMEDIATE	
Steady Flow	N/A
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

A circular stamp is located in the bottom right corner of the page. The text 'RECEIVED' is written in a large, bold, sans-serif font, curving along the top inner edge of the circle. Below it, the number '3037-123456' is printed in a smaller font, also following the curve of the circle. The stamp appears to be a receipt or a date stamp.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 11A

REMARKS:

By

Donny Snell
Pumper
(Position)

Witness

E-mail address

