



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-4-10 Operator Elmridge API #30-0 39-21176
Property Name Candado Well No. 18 Location: Unit Section 25 Township 26 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 131 Intermediate NA Casing 142 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	NA	142		
10 min	0		142		
15 min	0		142		
20 min	0		142		
25 min	0		142		
30 min	0		142		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		NA
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE


BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

By

Donny Snell
Pumper
(Position)

Witness



E-mail address