



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-8-10 Operator Elm Ridge API #30-0 39-21450
Property Name Candado Well No. 20 Location: Unit 3 Section 3 Township 26 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 128 Intermediate NA Casing 165 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	NA	165		
10 min	0		165		
15 min	0		165		
20 min	0		165		
25 min	0		165		
30 min	0		165		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	NA
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0


INTERMEDIATE NA

REMARKS:

By

Danny Snell
Danny Snell
(Position) pumper

Witness



E-mail address _____