

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

Oil CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			·	-		•			
Date of Test	<u>5-17-10</u> Operator			Ener	Energen Resources			3003921535	
Property Nam	e L	ITTLE FE	DERAL 29 1	Location	on: Unit F	Section 29 To	ownship 24	Range 3	
		(Well_Name	and Number)						
Pressure (Sh	ut-in or <u>Pro</u> c	ducing)	Tubing	165 Interme	ediate	Casing	<u>75</u> Bradenh	ead <u>-</u>	
OPEN	I BRADENH	EAD AND	INTERMEDIA	TE TO ATMOS	PHERE IND	DIVIDUALLY FOR	15 MINUTES E	ACH	
	Bradenhead			Interme	ediate		Bradenhead	Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	-	175				Steady Flow			
10 minutes	0	175			 	Surges			
15 minutes	6	175				Down to Nothing			
20 minutes		,,,				No Flow			
25 minutes			<u> </u>	:		Gas			
30 minutes						Gas and Water			
5 minute SI	8	175				Water			
_			· · · · · · · · · · · · · · · · · · ·	1	···	•			
<u>lf bradenhe</u>	ead flowed v	vater, che	eck all of the d	escriptions tha	t apply bel	ow:			
Clear	F	resh	Sal	tv	Sulfur	Bla	ck		
	-				_		2034	3036	
5 Minute Sh	nut-in B	radenhea	d 👄	Intermediat				IVED 3	
REMARKS:							WINTE		
							131 SECUMENT		
						-	1202020	318119	
· · · · · · · · · · · · · · · · · · ·							Or. T	11.00	
	1.	1 .		 					
By <u>Зи</u>	Then &	leice		W	itness				
LEN	then &	PERA	TOR						