



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-9-10 Operator Elm Ridge API #30-0 39-21739

Property Name Candado Well No. 22 Location: Unit _____ Section 4 Township 26 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 134 Intermediate NA Casing 152 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	NA	152		
10 min	0		152		
15 min	0		152		
20 min	0		152		
25 min	0		152		
30 min	0		152		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	NA
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

By Danny Snell
Pumper
(Position)

Witness _____

E-mail address _____

