



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-10 Operator Energen Resources API # 3003921989

Property Name CHACON JICARILLA D 14 Location: Unit B Section 15 Township 23 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 160 Intermediate        Casing 160 Bradenhead   

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>  </u>	<u>160</u>				Steady Flow		
10 minutes	<u>  </u>	<u>160</u>				Surges		
15 minutes	<u>  </u>	<u>160</u>				Down to Nothing		
20 minutes						No Flow	<u>  </u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	<u>  </u>	<u>160</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur        Black       

5 Minute Shut-in Bradenhead    Intermediate       

REMARKS:

By Luther Pierce

Witness       

LEASE OPERATOR

(Position)

