



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://nemrd.state.nm.us/ocd/District III/District.htm](http://nemrd.state.nm.us/ocd/District%20III/District.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-3-10 Operator Elm Ridge API # 30-039-22133
 Property Name Candado Well No. 24 Location: Unit Section 9 Township 26 Range 7
 Well Status (Shut-In or Production) Initial PSI: Tubing 0 Intermediate NA Casing 445 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
TIME		Int	Csg	Int	Csg
5 min	0	NA	445		
10 min	0		445		
15 min	0		445		
20 min	0		445		
25 min	0		445		
30 min	0		445		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		NA
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0INTERMEDIATE NA


REMARKS:

By

Danny Snell
pumper

(Position)

Witness



E-mail address