

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)												
Date of Test	5-10-500		Operator		Energen Resources			A	PI#	300	3922195	
Property Name			CARILLA D 15		Location: Unit K		Section 9) To	Township		Range	3
		(Well Name	e and Number)									
Pressure (Shu	ut-in or Proc	ducing)	Tubing	115	Interme	diate	Casing	115	ŏ Bra	adenh	ead <u>-</u>	<u>-</u>
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOSF	PHERE IND	IVIDUALLY	FOR 1	5 MINUT	res e	ACH	••••••
	Bradenhead BH Casing Intermediate			Intermediate Intermediate Casing					Braden Flow		Intermed Flower	
<u>Time</u> 5 minutes	Blowdown	Monitor	Monitor	BI	lowdown	Monitor	Steady	/ Flow				
10 minutes	<u> </u>	115					Ī	urges				
15 minutes	<u>4</u>	115					Down to No	othing				
20 minutes							No	Flow				
25 minutes							<u> </u>	Gas				
30 minutes							Gas and	Water Water	<u> </u>			
5 minute SI	0	115						vvaler		<u> </u>	<u> </u>	······································
<u>lf bradenhe</u>	ad flowed w	vater, che	eck all of the d	escrip	tions tha	t apply bel	ow:					
Clear	Fı	resh _	Sal	ty _		Sulfur		Blad	k		_	
5 Minute Sh	u t-in B	radenhea	d <u>-e</u>	Interr	nediat			į	20031 PE	A CE UNIE	VED M.DISE3	01011727
									S OILC	ONS, D	N. DISE 8	ω/
									1.50 MILE	Zame.		<u> </u>
						<u></u>			30	~ UCE	0600	
By Zui	then?	Vince			Wi	tness						
ву <u>Ди</u> <u>LEB</u>	15E 0	PERN	ton									

(Position)