



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distr.htm](http://emnr.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-25-10 Operator GREAT WESTERN API #30-0 39-23347
Property Name Crow Mesa Well No. 2 Location: Unit G Section 19 Township 25N Range 7W
Well Status (Shut-In or ~~Producing~~) Initial PSI: Tubing 327 Intermediate na Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

AK

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME	<u>0</u>		<u>0</u>		
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS			
BRADENHEAD	INTERMEDIATE		
Steady Flow			
Surges			
Down to Nothing			
Nothing	X		
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS: Packer in well.

By CODY HANNAH

Witness

LEASE OPERATOR

(Position)

E-mail address cody@walsheng.net

