



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-24-2010 Operator Energen Resources API # 3003924285

Property Name CARRACAS UNIT 13 A 14 Location: Unit N Section 13 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing ⊖ Intermediate ⊖ Casing 49 Bradenhead ⊖

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flowed	Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	⊖	49				Steady Flow	⊖
10 minutes	⊖	51				Surges	⊖
15 minutes	⊖	48				Down to Nothing	⊖
20 minutes	⊖	51				No Flow	⊖
25 minutes	⊖	51				Gas	⊖
30 minutes	⊖	51				Gas and Water	⊖
5 minute SI	⊖	49				Water	⊖

Handwritten note:
If valve
no good -
were they
able to close
for 2 hours
pure

If bradenhead flowed water, check all of the descriptions that apply now:

Clear NA Fresh NA Salty NA Sulfur NA Black NA

5 Minute Shut-in Bradenhead ⊖ Intermediate ⊖

REMARKS: Had to change valve it was no good anymore

By [Signature]
Lease operator
(Position)

Witness

