



NEW MEXICO ENERGY MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

*looks
producing*

TEST REPORT

(above address)

Date of Test 6.22.2010 Energen Resources API # 3003924415

Property Name CARRACAS UNIT FR 114 Location: Unit I Section 35 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 100# Intermediate n/a Casing 100# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0#	100#	n/a	n/a	n/a	Steady Flow		
10 minutes	0	100	n/a			Surges		
15 minutes	0	100				Down to Nothing	✓	
20 minutes	0	100				No Flow		
25 minutes	0	100				Gas		
30 minutes	0	100				Gas and Water		
5 minute SI	0#	120				Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0# Intermediate n/a

REMARKS:

well m off cycle (plugs lft)



By Mike Howe

Witness _____

Sr. Core Operator

(Position)