



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST
(Submit 2 copies to above)

Date of Test 6-13-2010 Operator Energ Resour *to beginning* 3003924461

Property Name CARRACAS UNIT FR 101 Location: Unit K Section 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 170# Intermediate N/A Casing 84# Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0#</u>	<u>84#</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	Steady Flow	
10 minutes	<u>0</u>	<u>84</u>				Surges	
15 minutes	<u>0</u>	<u>84</u>				Down to Nothing	
20 minutes	<u>0</u>	<u>84</u>				No Flow	☒
25 minutes	<u>0</u>	<u>84</u>				Gas	
30 minutes	<u>0</u>	<u>84</u>				Gas and Water	
5 minute SI	<u>04</u>	<u>105#</u>	<u>✓</u>	<u>✓</u>	<u>✓</u>	Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0# Intermediate N/A

REMARKS:



By Michael Howe Witness
Sr. Lease Operator
(Position)