



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/9/2010 Operator Energen Resources API # 3003925999

Property Name SAN JUAN 32 5 UNIT 9R Location: Unit A Section 31 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 90 Intermediate NA Casing 90 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>90</u>	<u>NA</u>	<u>NA</u>		Steady Flow		<u>NA</u>
10 minutes	<u>0</u>	<u>90</u>				Surges		
15 minutes	<u>0</u>	<u>90</u>				Down to Nothing		
20 minutes	<u>0</u>	<u>90</u>				No Flow	<u>X</u>	
25 minutes	<u>0</u>	<u>90</u>				Gas		
30 minutes	<u>0</u>	<u>90</u>				Gas and Water		
5 minute SI	<u>0</u>	<u>90</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate NA

REMARKS:

By Richard Fairbanks Witness
Lease Operator
(Position)

