

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	Pate of Test 7/7/10		Operator —		Energen Resources			API# 30	3003926128	
Property Name		SAN JUAN 32 5 UNIT 10A (Well Name and Number)			Location: Unit J Section 32			ownship 32	Range 5	
Pressure (Shu	ıt-in or Proc	lucing)	Tubing _	60	Interme	ediate <i>M</i>	4 Casing 7	O Braden	head <u>O</u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOS	PHERE IND	IVIDUALLY FOR	15 MINUTES	EACH	
	Bradenhead			Intermediate			Bradenhead	I Intermediate		
Time	BH Blowdown	Casing Monitor	Intermediate Monitor		ermediate	Casing Monitor		Flowed	Flowed	
5 minutes				-		Monto	Steady Flow			
10 minutes	0	70	<u> </u>		<u>NA</u>	 	Surges			
15 minutes		70			-}	<u> </u>	Down to Nothing			
	0	70			<u> </u>	 	No Flow			
20 minutes	0	70				<u> </u>	Gas			
25 minutes	0	70				<u> </u>	Gas and Water			
30 minutes		70					Water			
5 minute \$I	0	70			-		vvater			
If bradenhe Clear 5 Minute St	F	vater, che resh _ radenhea		alty	ntions the	at apply below Sulfur	ow: Bla	12345 JEC	2010 2	
REMARKS:			and the second		- 			1 E. O. O.	S. DIV. DIST. 3	
									2903	
ву <u>Rich</u> Leas	ard Fo	airbant erato.	<u>-</u> S		w	/itness				
	•	(Positio								