



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/7/10 Operator Energy Resources API # 3003926597

Property Name SAN JUAN 32 5 UNIT 113 Location: Unit N Section 32 Township 32 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65 Intermediate NA Casing 65 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>65</u>	<u>NA</u>			Steady Flow		
10 minutes	<u>0</u>	<u>65</u>	<u>NA</u>			Surges		
15 minutes	<u>0</u>	<u>65</u>	<u>NA</u>			Down to Nothing		
20 minutes	<u>0</u>	<u>65</u>	<u>NA</u>			No Flow	<u>X</u>	
25 minutes	<u>0</u>	<u>65</u>	<u>NA</u>			Gas		
30 minutes	<u>0</u>	<u>65</u>	<u>NA</u>			Gas and Water		
5 minute SI	<u>0</u>	<u>65</u>	<u>NA</u>			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate NA

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Richard Fairbanks Witness \_\_\_\_\_  
Lease Operator  
(Position)

