

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			•				·			
Date of Test 7/7/10		110	Operator		Energen Resources			API#	300	3926616
Property Name		(Well Name	2 5 UNIT 10B and Number) Tubing				Section 32 1		ip 32 —— Bradenh	
OPEN	I BRADENHI	EAD AND	INTERMEDIA	TE TO	ATMOS	PHERE IND	IVIDUALLY FOR	15 MIN	IUTES E	ACH
Time	Bradenhead BH Casing Intermediate Blowdown Monitor Monitor			Intermediate Intermediate Casing Blowdown Monitor					enhead owed	Intermediate Flowed
5 minutes	0	120	NA	-	NA		Steady Flow			
10 minutes	0	120			1		Surges			
15 minutes	0	120					Down to Nothing No Flow			
20 minutes	0	120					Gas		<u> </u>	
25 minutes	0	120			 		Gas and Water			
30 minutes	0	120		—	<u> </u>	 	Water		,	1
5 minute SI	0	120	·	J L		1	j			
If bradenhed Clear 5 Minute S REMARKS:	F	vater, che resh radenhead	ck all of the d	lty	mediat	at apply bel Sulfur	<u>ow:</u> Bla	ack 234567	RECE OIL CONS	13147576718 192027 2010 .DIV. DIST. 3
					•		· · · · · · · · · · · · · · · · · · ·	_	-067	.290-
By Rich	ad Fai e Oper	bank ofer (Position			w	/itness				