

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(Oubilli	t z copies to at	ove addre	33)				
Date of Test	7/7/	7/7/10 Operator BULLRIDGE 100		Energ	Energen Resources			3003926950		_
Property Name	· · ·			Location: Unit P Section 33			ownship	32	Range 5	
		(Well Name	and Number)							
Pressure (Shu	ıt-in or Proc	ducing	Tubing _	O Interme	diate <u></u> <u> </u>	Casing <u>3</u>	<u>?/О</u> ві	radenhe	ead <u>O</u>	_
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINU	TES E	ACH	
	Bradenhe	ad	Interme	diate		Brader	head	Intermedia	ł o	
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flov		Flowed	
5 minutes	Blowdown		A / A	Blowdown	Worldor	Steady Flow		_		_
10 minutes	$\frac{\mathcal{O}}{\mathcal{O}}$	310	NA			Surges	<u> بسي</u>			
15 minutes	0	310				Down to Nothing				_
20 minutes	0	310				No Flow	· - ×	,		
25 minutes	0	310				Gas				_
30 minutes		310				Gas and Water				
	0	310				Water	•			_
5 minute SI		310				J		09992	37476	
If bradenhe	ad flowed v	vater che	ck all of the d	escriptions tha	t apply bel	ow:	(69°)		13 74 75 76 75 IVED 30 2010 5	
ii bradeiiie	au noweu i	vator, one	ok un or the u	coorpaione and	t apply bo		9	FCE	IVED &	1
Clear	F	resh _	Sa	lty	Sulfur	Bla	acko _	MANAGE TO SERVICE TO S	2010	إذ
			•		. 4.4		15	II. CONS.	DIV DIST. 3 A	
5 Minute Sh	nut-in E	Bradenhea	d <u><i>O</i></u>	Intermediat	_NA_		Le de	, A	ر المالي مالي	1
							1.6	658511	COLCULATION OF THE STREET	
REMARKS:										
				· · · · · · · · · · · · · · · · · · ·				-		
										_
	, , ,									
By <u>Kick</u>	nard to	airban	ks	Wi	tness					_
Leac	e, Ope	rator								
	,	(Positio								