



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/7/10 Operator Energen Resources API # 3003927272

Property Name STATE BANCOS 100 Location: Unit H Section 32 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65 Intermediate NA Casing 65 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>65</u>	<u>NA</u>	<u>NA</u>		Steady Flow		
10 minutes	<u>0</u>	<u>65</u>				Surges		
15 minutes	<u>0</u>	<u>65</u>				Down to Nothing	<u>X</u>	
20 minutes	<u>0</u>	<u>65</u>				No Flow		
25 minutes	<u>0</u>	<u>65</u>				Gas	<u>X</u>	
30 minutes	<u>0</u>	<u>65</u>				Gas and Water		
5 minute SI	<u>0</u>	<u>65</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

Slight Blow down to Nothing. No Build up

By Richard Fairbanks Witness _____
Lease Operator
(Position)