

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	7/9	7/9/2010		Energ	Energen Resources		API#	3003927273	
Property Name	e S	STATE BANCOS 100S (Well Name and Number)			Location: Unit D Section 32 Township			32 Range 5	
Pressure (Shu	ut-in or Proc	ducing	Tubing _	50 Interme	diate _ <i>_//</i> _	A Casing <u>I</u>	Bra	denhead <u>O</u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	HERE IND	IVIDUALLY FOR	15 MINUT	ES EACH	
Time	Bradenhead BH Casing Intermediate Blowdown Monitor Monitor			Interme	Casing		Bradenh Flowe	nead Intermediate ed Flowed	
5 minutes	Blowdown			Blowdown	Monitor	Steady Flow		114	
10 minutes		<i>50</i>	<u>NA</u>	10H		Surges		1	
15 minutes	<u> </u>	50		-		Down to Nothing		- 	
20 minutes		50				No Flow	×		
25 minutes	0	50				Gas			
30 minutes	$\frac{\mathcal{O}}{\mathcal{O}}$	50				Gas and Water			
5 minute SI		S) S)				Water			
	F		Sal	escriptions that	t apply bel	B)	OF OCTOPS	01112131218 2010 2010 DIV. DIST. 3	
By <u>Rich</u>	and Fa	uirban	ks_	Wi	tness				
Leas	e Ope	rator	· · · · · · · · · · · · · · · · · · ·						
		(Position	1)						