



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/8/2010 Operator Energex Resources API #30-039-29987

Property Name San Juan 32-5 Unit Well No. 116 Location: Unit 0 Section 27 Township 32N Range 06W

Well Status (Shut-In or Producing) Tubing 30 Intermediate NA Casing 80 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>NA</u>	<u>80</u>
10 minutes	<u>0</u>	<u> </u>	<u>80</u>
15 minutes	<u>0</u>	<u> </u>	<u>80</u>
20 minutes	<u>0</u>	<u> </u>	<u>80</u>
25 minutes	<u>0</u>	<u> </u>	<u>80</u>
30 minutes	<u>0</u>	<u> </u>	<u>80</u>

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
		<u>NA</u>
Steady Flow		<u> </u>
Surges		<u> </u>
Down to Nothing		<u> </u>
Nothing	<u>X</u>	<u> </u>
Gas		<u> </u>
Gas & Water		<u> </u>
Water		<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:



By Richard Fairbanks

Witness _____

Lease Operator
(Position)

E-mail address _____