



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-12-10 Operator Williams Rod. API #30-0 39-30937
Property Name Rosa Unit Well No. 634B Location: Unit H Section 22 Township 31 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 266 Casing -2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min				0	-4
10 min				0	-4
15 min				0	-4
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	air
Nothing	vacume
Gas	RCVD OCT 12 '10
Gas & Water	OIL CONS. DIV.
Water	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 1

REMARKS:

~~There is two intermediates on this well - has not been~~
~~completed - no tubing - BH vacume when opened - dead after~~
~~3 seconds - Intermediate had blow to 40 seconds dead~~
By Matt Basye ^{at 1 minute 30 seconds} Witness Monica Kuehling
Lead
(Position)

E-mail address matt.basye@williams.com

There is a steel pipe ran to 80 feet which is a conductor
pipe with a 2" valve. Nothing when opened (Don gauge)