

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-20-		-10 Operator		Ener	Energen Resources		.PI# 300	3003960021	
Property Name	e	HILL 5			Location: Unit C Section 20		ownship 24	Range 3	
		(Well Name	and Number)						
Pressure (Shi	ut-in or Proc	ducing)	Tubing <u>/</u>	16 Interme	ediate	Casing <u>//</u>	<u>る</u> Bradenh	ead 👉	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOS	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
Γ	Bradenhead			Interme	ediate		D. Loub ad	1.4	
<u>Time</u>	ВН	Casing	Intermediate	Intermediate	, -		Flowed	Intermediate Flowed	
5 minutes	Blowdown	Monitor	Monitor	Blowdown	Monitor	Steady Flow			
10 minutes	-6	150				Surges			
15 minutes	6	150				Down to Nothing			
20 minutes	0	150			 	No Flow			
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI	0	15 D				Water			
If bradenhe Clear 5 Minute Sh	F	vater, che resh radenhea	Salt		at apply bel	Bla	2522 RECE	1010 3	
							الله الله الله الله الله الله الله الله	V. DIST. 3	
							OC 6	r ar ir al ray	
By <u>Aut</u>	then Pl	ierce Intor		w	itness				

(Position)