

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			`		•		•		
Date of Test	5-19-10 Operator			r	Energen Resources			API# 30	04320499
Property Name		JICARI	JICARILLA 55 1			Location: Unit K Section 35		ownship 23	Range 3
		(Well Name	and Number)						
Pressure (Sh	ut-in or Pro	ducing)	Tubing _	130	Interme	ediate	Casing <u>/ 9</u>	75 Bradeni	nead <u> </u>
OPEN	I BRADENH	EAD AND	INTERMEDIA	ATE TO	ATMOSI	PHERE INC	DIVIDUALLY FOR	15 MINUTES I	EACH
[Bradenhead			Intermediate]	Bradonhoad	Intermediate	
<u>Time</u>	BH Blowdown	Casing	Intermediate		ermediate	Casing		Flowed	Flowed
5 minutes		Monitor	Monitor	-	lowdown	Monitor	Steady Flow		
10 minutes	<u> </u>	145					Surges		
15 minutes	-6	145					Down to Nothing		
20 minutes		145				<u> </u>	No Flow		
							Gas		
25 minutes						 	Gas and Water		
30 minutes							Water		
5 minute SI	0	145		J L]		
<u>lf bradenhe</u>	ad flowed v	vater, che	ck all of the c	lescrip	tions tha	t apply bel	ow:		
Clear Fresh Salty Sulfur							Black		
5 Minute Sh	n ut-in B	radenhead	d <u>-6-</u>	Interr	nediat			A RECE	1VED 101112
								OIL CONS. D	
 						,		10,45	Where ×/
<u>,</u>								\$20 <u>2</u> 5026	1812
ву <u>Ди</u>	then Se	- ENTLA			Wi	tness			
		(Position)						