



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-2010 Operator Energen Resources API # 3003906743

Property Name JICARILLA WEST 2 Location: Unit A Section 6 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 150 Intermediate Casing 155 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>2</u>	<u>155</u>				Steady Flow ☒	
10 minutes	<u>4.5</u>	<u>155</u>				Surges	
15 minutes	<u>6</u>	<u>155</u>				Down to Nothing	
20 minutes	<u>7</u>	<u>155</u>				No Flow	
25 minutes	<u>7</u>	<u>155</u>				Gas	
30 minutes	<u>10</u>	<u>155</u>				Gas and Water	
5 minute SI	<u>2</u>	<u>155</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur

5 Minute Shut-in Bradenhead 2 psi Intermediate

REMARKS:

Bradenhead pressure was a steady flow.

By Alex Hwang Witness

Field Operator

(Position)

