



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-19-2010 Operator Energex Resources API # 3003907140

Property Name JICARILLA 119 N 6 Location: Unit A Section 7 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 35 Intermediate Casing 45 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	45				Steady Flow	
10 minutes	0	45				Surges	
15 minutes	0	45				Down to Nothing	
20 minutes						No Flow	✓
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0	45				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

By Alan Harvey

Witness

Field Operator

(Position)

