



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/1/10 Operator Energen Resources API # 3003922786

Property Name BIXLER RANCH 1 Location: Unit E Section 26 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 170 Intermediate N/A Casing 180 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	No Blw	185	N/A	N/A	N/A		
10 minutes	No Blw	190	N/A	N/A	N/A		
15 minutes	No Blw	195	N/A	N/A	N/A		
20 minutes	No Blw		N/A				
25 minutes	No Blw		N/A				
30 minutes	No Blw		N/A				
5 minute SI	0	205	N/A				

Steady Flow

Surges

Down to Nothing

NO FLOW

NO FLOW

Gas

Oil and Water

Water

RECEIVED

JUL 1 2010

OIL CONS. DIV. DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS: Bradenhead had Nothing

By [Signature] Witness _____
Pumper
(Position)