



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/1/10 Operator Energen Resources API # 3003923261

Property Name BIXLER RANCH 2 Location: Unit M Section 26 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) 260 Intermediate N/A Casing 180 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Very Light Blow	180	N/A	N/A	N/A	Steady Flow	Very Light Blow	N/A
10 minutes	Very Light Blow	180	N/A	N/A	N/A	Surges		N/A
15 minutes	Very Light Blow	180	N/A	N/A	N/A	Down to Nothing		NA
20 minutes	Very Light Blow	180	N/A	N/A	N/A	No Flow		NA
25 minutes	Very Light Blow	180	N/A	N/A	N/A	Gas		N/A
30 minutes	Very Light Blow	180	N/A	N/A	N/A	Gas and Water		N/A
5 minute SI	3	180	N/A	N/A	N/A	Water		NA

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead _____ Intermediate N/A

REMARKS: Very Light Blow For 30 min.

By [Signature] Witness _____
Pumper
(Position)

