



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-17-2010 Operator Energen Resources API # 3003926575

Property Name JICARILLA 152W 2M Location: Unit J Section 5 Township 26 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65 Intermediate        Casing 85 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	85				Steady Flow	
10 minutes	0	85				Surges	
15 minutes	0	85				Down to Nothing	
20 minutes	0	85				No Flow	✓
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0	85				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur       

5 Minute Shut-in Bradenhead 0 Intermediate       

REMARKS:

By Alex Harvey Witness         
Field Operator  
(Position)

