

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			•				•			
Date of Test	5-21	5-21-2010 Operator			Energen Resources				300	3982352
Property Nam	e	KLEIN 8				Location: Unit A Section 34			ip <u>26</u>	Range 6
		(Well Name	and Number)							
Pressure (Sh	ut-in or Proc	ducing	Tubing <u>/</u>	35	Interme	diate	Casing <u>/</u>	40_	Bradenh	ead <u>O</u>
OPEN	I BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOSI	PHERE IND	IVIDUALLY FOR	15 MIN	IUTES E	ACH
-	Bradenhead				Interme	diate		Brad	enhead	Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	1 1	ermediate lowdown	Casing Monitor			owed	Flowed
5 minutes	0	140		–			Steady Flow	/		
10 minutes	0	140					Surges	3		
15 minutes	0	140					Down to Nothing			
20 minutes							No Flov			
25 minutes			<u>,, , , , , , , , , , , , , , , , , , ,</u>				Gas		·	
30 minutes							Gas and Wate			
5 minute SI	0	140					Wate	r 		
If bradenhead flowed water, check all of the descriptions that apply below: Clear Fresh Salty Sulfur Black RECEIVED 5 Minute Shut-in Bradenhead O Intermediat REMARKS:										
Ву <i></i> Д	lu 7	for	neta		Wi	itness				
		(Position								