



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test June 9, 2010 Operator Elm Ridge Exploration API #30-0 39-05088

Property Name AXI Apache A Well No. 3 Location: Unit M Section 10 Township 23N Range 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 130 Intermediate NA Casing 130 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	○		130		
10 min	○		130		
15 min	○		130		
20 min	○		130		
25 min	○		130		
30 min	○		130		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD ○ INTERMEDIATE _____

REMARKS:

Well is shut in - Gas Sales Line Leak

By Joe J. Lavato, Jr.
Pumper
(Position)

Witness _____

E-mail address _____

