



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test June 7, 2010 Operator Elm Ridge Exploration API #30-0 39-05211

Property Name AXI Apache C Well No. 3 Location: Unit M Section 34 Township 24N Range 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 85 Intermediate NA Casing 86 Bradenhead C

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	<u>0</u>		<u>86</u>		
10 min	<u>0</u>		<u>86</u>		
15 min	<u>0</u>		<u>86</u>		
20 min	<u>0</u>		<u>86</u>		
25 min	<u>0</u>		<u>86</u>		
30 min	<u>0</u>		<u>86</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____


5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Well is shut in - GAS Sales Line Leak



By Joe J. Louwette, Jr.
Pumper
(Position)

Witness _____

E-mail address _____