



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test June 7, 2010 Operator Elm Ridge Exploration API #30-0 39-05212

Property Name AXI Apache C Well No. 4 Location: Unit P Section 33 Township 24N Range 5E

Well Status (Shut-In) or Producing) Initial PSI: Tubing 81 Intermediate NA Casing 81 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	0		81			Steady Flow	
10 min	0		81			Surges	
15 min	0		81			Down to Nothing	
20 min	0		81			Nothing	✓
25 min	0		81			Gas	
30 min	0		81			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____


5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Well is Shut IN. - GAS SALES LINE LEAK



By Joe J. Lavato, Jr.
Pumper.
(Position)

Witness _____

E-mail address _____