

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of	Test_	5-	4-10		_ Operator_	Elm Ridge	API #	\$30-0 <u>39-05326</u>	
Property Name CRADE FEED Well No. 7 Location: Unit C Section 29 Township 2411 Range 161									
Well Status(Shut-In or Producing) Initial PSI: Tubing 29 Intermediate Casing 36 Bradenhead 0									
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
Testing	PRESSURE Bradenhead INTERM BH Int Csg Int				RM Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE			
TIME 5 min_	<i>O</i>	III	36	1111	Csg	Steady Flow			
10 min_	0		34			Surges			
15 min_	0		36			Down to Nothir	ng		
20 min_		-			<u> </u>	Nothing	/		
25 min_						Gas			
30 min_						Gas & Water			
Water									
If bradenhead flowed water, check all of the descriptions that apply below:									
(CLEAF	t	FRESH	S	SALTY	SULFUR	_BLACK	S DECEIVED	23.72A
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK PECEIVED 5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE REMARKS:									
					-			2851-1E0	
	_								
By Witness Witness (Position)									
<i>op</i> :	er Alor (Positio	on)							
E-mail address									