



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-4-10 Operator Devon API #30-0 3924733
Property Name NEBU Well No. 499 Location: Unit Section 20 Township 31^N Range 6W
Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate Casing 2.5 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	-	2.5		
10 min	0	-	2.5		
15 min	0	-	2.5		
20 min	0	-	2		
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

By [Signature]
Tester
(Position)

Witness [Signature]
Larry Rouse

E-mail address

