



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 6-1-10 Operator Devon API #30-0 3927701
Property Name NEBU Well No. 495A Location: Unit Section 30 Township 31^N Range 6^W
Well Status(Shut-In or Producing) Initial PSI: Tubing 1 Intermediate Casing 5 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	-	5		
10 min	0	-	5		
15 min	0	-	5		
20 min	0	-	5		
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

By Jared Winters
Tester
(Position)

Witness Be Ryan

E-mail address